



Gas spring POWERLINE

Mounting variations


2480.007.00500




2480.008.00500³⁾




2480.010.00500.095³⁾
2480.010.00500.180*³⁾




2480.022.00500




2480.044.00500²⁾




2480.044.03.00500²⁾




2480.055.00500



2480.057.00500



2480.064.00500⁴⁾



Note:

- ²⁾ Attention:
The spring force must be absorbed by the stop Surface!
- ³⁾ Not for use with composite connection.
- ⁴⁾ Square collar flange, non-rotating, fixing for composite connection.
- ⁵⁾ Machine screws with hexagonal socket (compact head recommended)