



# Gas spring POWERLINE

## Mounting variations



**Note:**

2) Attention:  
The spring force must be absorbed by the stop Surface!

4) Square collar flange, non-rotating, fixing for composite connection.

5) Machine screws with hexagonal socket (compact head recommended)