



Gas spring POWERLINE with reinforced spring base

Mounting variations


2480.007.01000




2480.011.01000




2480.011.01000.2




2480.022.01000




2480.044.03.01000²⁾




2480.057.01000



2480.057.03.01000



2480.064.01000⁴⁾



Note:

- ²⁾ Attention:
The spring force must be absorbed by the stop Surface!
- ⁴⁾ Square collar flange, non-rotating, fixing for composite connection.
- ⁵⁾ Machine screws with hexagonal socket (compact head recommended)