



# COMPACT GAS SPRING MOUNTING VARIATIONS


2480.022.05000




2480.044.05000<sup>2)</sup>




2480.044.03.05000<sup>2)</sup>




2480.052.11800




2480.055.05000




2480.057.05000



2480.064.05000<sup>4)</sup>



## Mounting example:



with Adapter Baseplate

## Note:

- <sup>2)</sup> Attention:  
The spring force must be absorbed by the stop Surface!
- <sup>4)</sup> Square collar flange, non-rotating, fixing for composite connection.
- <sup>5)</sup> Machine screws with hexagonal socket (compact head recommended)

## Mounting examples:

