



GAS SPRING WITH THROUGH BORE PASSAGE MOUNTING VARIATIONS


2480.055.01500



2480.057.01500






2480.064.01500⁴⁾



Note:

- ⁴⁾ Square collar flange, non-rotating, fixing for composite connection.
- ⁵⁾ Machine screws with hexagonal socket (compact head recommended)

Mounting examples:



see Note!

