



# GAS SPRING MOUNTING LINE MOUNTING VARIATIONS


2480.044.00150<sup>2)</sup>  




2480.044.03.00150<sup>2)</sup>  



2480.055.00150  



2480.057.00150  



## Note:

<sup>2)</sup> Attention:  
The spring force must be absorbed  
by the stop Surface!

## Mounting examples:

